

# GUÍA BUJÍAS

## SUZUKI

MODELO	NGK	MODELO	NGK	IRIDIUM	MODELO	NGK	IRIDIUM			
DT2	1986-90	<b>NGKBR4HS</b>	DT30	1983-85	<b>NGKBR7HS-10</b>	DT85WT	2001	<b>NGKB8HS-10</b>		
DT2	1991-99	<b>NGKBR5HS</b>	DT30C	1988-00	<b>NGKBR7HS-10</b>	DT85WT	1995-96	<b>NGKB8HS-10</b>		
DT2.2	1992	<b>NGKBR5HS</b>	DT30E	1983	<b>NGKBR7HS-10</b>	DT90	-2000	<b>NGKBR8HCS-10</b>		
DT4	1988-92	<b>NGKBP5HS</b>	DT40	-1983	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT90	2001	<b>NGKBR8HS-10</b>	
DT4	1993-01	<b>NGKBP5HS</b>	DT40C	1986-99	<b>NGKB8HS-10</b>	DT90TC	1996-97	<b>NGKBR8HS</b>	<b>NGKBR8HIX</b>	
DT4,5		<b>NGKBR6HS</b>	DT40C/CR/TC	1998	<b>NGKB8HS-10</b>	DT90TC	-1995	<b>NGKBR8HCS-10</b>		
DT4L/S	1994	<b>NGKBP5HS</b>	DT40W	1995	<b>NGKB7HS-10</b>	DT90TC	1998	<b>NGKBR8HS-10</b>		
DT4L/S	-1993	<b>NGKBP5HS</b>	DT40WK	1998	<b>NGKB7HS-10</b>	DT100	2001	<b>NGKBR8HS-10</b>		
DT5	1986-92	<b>NGKBP6HS</b>	DT40WK	-1997	<b>NGKB7HS</b>	DT100	1996-00	<b>NGKBR8HS-10</b>		
DT5	1993-94	<b>NGKBP6HS</b>	DT48M	2001	<b>NGKB8HS-10</b>	DT100	1990-95	<b>NGKBR8HCS-10</b>		
DT5	1995-00	<b>NGKBR6HS</b>	DT48M	-2000	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT100	2000	<b>NGKBR8HCS-10</b>	
DT5W	1986-92	<b>NGKBR6HS</b>	DT50	1979-83	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT100TC	-1995	<b>NGKBR8HCS-10</b>	
DT5Y	1998-01	<b>NGKBP7HS-10</b>	DT50	-1978	<b>NGKB7HS</b>	DT100TC	1998	<b>NGKBR8HS-10</b>		
DT6	1986-92	<b>NGKB6HS-10</b>	DT50	1984-89	<b>NGKB8HS-10</b>	DT100TC	1996-97	<b>NGKBR8HS</b>	<b>NGKBR8HIX</b>	
DT6	1993-02	<b>NGKBR6HS</b>	DT50ACR	1994-96	<b>NGKB8HS-10</b>	DT115	-1990	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	
DT6	-1985	<b>NGKB6HS</b>	DT50ACR	1993	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT115	1992	<b>NGKBR8HCS-10</b>	
DT6	1995-99	<b>NGKBR6HS-10</b>	DT50C	1984-00	<b>NGKB8HS-10</b>	DT115C	1991-93	<b>NGKBR8HCS-10</b>		
DT6S/5PS	-1992	<b>NGKBR6HS</b>	DT50K		<b>NGKB7HS</b>	DT115C	-1990	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	
DT7.5		<b>NGKBR6HS</b>	DT50M/DT50	1986-89	<b>NGKB8HS-10</b>	DT115C	2001	<b>NGKBR8HS-10</b>		
DT8	1986-02	<b>NGKBP6HS</b>	DT50M/DT50	-1985	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT115S	1996	<b>NGKBR8HS-10</b>	
DT8C	1988-97	<b>NGKBR6HS-10</b>	DT50M/DT50	2001	<b>NGKBR8HS-10</b>	DT115STC	1996	<b>NGKBR8HS-10</b>		
DT9		<b>NGKB6HS-10</b>	DT55C	1988-98	<b>NGKBR8HS-10</b>	DT115TC	-1988	<b>NGKB8HS-10</b>		
DT9.9	1986-99	<b>NGKBR7HS-10</b>	DT55M/MQ	-2000	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT115TC		<b>NGKBR8HCS-10</b>	
DT9.9	1977-78	<b>NGKB7HS</b>	DT55M/MQ	2001	<b>NGKBR8HS-10</b>	DT115TC (EFI)		<b>NGKBR8HS-10</b>		
DT9.9	1879-84	<b>NGKBR6HS</b>	DT55TC/CRQ	1998	<b>NGKB8HS-10</b>	DT140	1992	<b>NGKBR8HCS-10</b>		
DT9.9	1976	<b>NGKB6HS</b>	DT60		<b>NGKB8HS-10</b>	DT140	-1990	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	
DT9.9C	1988-97	<b>NGKBR6HS-10</b>	DT60C	2001	<b>NGKBR8HS-10</b>	DT140 EFI	1996	<b>NGKBR8HS-10</b>		
DT9.9E	1982	<b>NGKB6HS</b>	DT60C	1986-87	<b>NGKB8HS-10</b>	DT140C	1991-96	<b>NGKBR8HCS-10</b>		
DT9.9E	1984	<b>NGKB7HS</b>	DT65/T	-1983	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT140C	-1990	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>
DT9.9E	1983	<b>NGKBR7HS-10</b>	DT65C	1988-99	<b>NGKBR8HS-10</b>	DT140C EFI	1997	<b>NGKBR8HCS-10</b>		
DT9.9K	1985-86	<b>NGKB6HS</b>	DT65TC	1994-95	<b>NGKBR8HS-10</b>	DT140T	-2000	<b>NGKBR8HCS-10</b>		
DT9.9K	-1985	<b>NGKBR6HS</b>	DT75/85	1990-92	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT140T	2001	<b>NGKBR8HS-10</b>	
DT9.9K	1986-90	<b>NGKB6HS</b>	DT75/85	1993-00	<b>NGKBR8HS-10</b>	DT140TC	-2000	<b>NGKBR8HCS-10</b>		
DT9.9P	-1983	<b>NGKBP6HS</b>	DT75C	2001	<b>NGKBR8HS-10</b>	DT140TC EFI		<b>NGKBR8HS-10</b>		
DT15	1986-02	<b>NGKBR7HS-10</b>	DT75C	1993-00	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT150	1987-02	<b>NGKBR8HS-10</b>	
DT15C	1989-97	<b>NGKBR7HS-10</b>	DT75M	2001	<b>NGKBR8HS-10</b>	DT150G		<b>NGKBR8HS-10</b>		
DT15K	-1985	<b>NGKBR6HS</b>	DT75M	-2000	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT150S		<b>NGKBR8HS-10</b>	
DT15K	1986	<b>NGKB6HS</b>	DT75TC	-2000	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT150SS		<b>NGKBR8HS-10</b>	
DT20	1997-00	<b>NGKBR7HS-10</b>	DT77C	2001	<b>NGKBR8HS-10</b>	DT150STC		<b>NGKBR8HS-10</b>		
DT20/P	-1985	<b>NGKBR7HS</b>	DT85	-1992	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT150TC	1989	<b>NGKBR8HS-10</b>	
DT20/P	1986	<b>NGKBR7HS-10</b>	DT85C	2001	<b>NGKBR8HS-10</b>	DT150TC EFI		<b>NGKBR8HS-10</b>		
DT20K	-1985	<b>NGKBR7HS-10</b>	DT85C	1993-00	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT175	1989-02	<b>NGKBR8HS-10</b>	
DT20K	1986-87	<b>NGKB7HS-10</b>	DT85C	-1992	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT175TC	-1988	<b>NGKB8HS-10</b>	
DT25	-1985	<b>NGKBR7HS</b>	DT85M	2001	<b>NGKBR8HS-10</b>	DT175TC	1989	<b>NGKBR8HS-10</b>		
DT25	2000-01	<b>NGKBR7HS-10</b>	DT85M	-2000	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT200	1989-02	<b>NGKBR8HS-10</b>	
DT25C	1989-97	<b>NGKBR7HS-10</b>	DT85MQ	1995-96	<b>NGKB8HS-10</b>	DT200G		<b>NGKBR8HS-10</b>		
DT25E	1983-85	<b>NGKBP7HS-10</b>	DT85Q	2001	<b>NGKB8HS-10</b>	DT200T		<b>NGKBR8HS-10</b>		
DT25E	-1982	<b>NGKB7HS</b>	DT85Q	-2000	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT200TC	1989	<b>NGKBR8HS-10</b>	
DT25E	1986	<b>NGKBR7HS-10</b>	DT85TC	-2000	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT200V		<b>NGKBR8HS-10</b>	
DT25K	1986	<b>NGKBR7HS-10</b>	DT85TC	2001	<b>NGKBR8HS-10</b>	DT225	1991-02	<b>NGKBR8HS-10</b>		
DT28/P/E		<b>NGKB7HS</b>	DT85W	2001	<b>NGKB8HS-10</b>	DT225TC		<b>NGKBR8HS-10</b>		
DT30	1986	<b>NGKBR7HS-10</b>	DT85W	-2000	<b>NGKB8HS</b>	<b>NGKBR8HIX</b>	DT225TCL EFI		<b>NGKB8HS</b>	<b>NGKBR8HIX</b>